## Work Order ID 61848

September 8, 2010 8:31:43 AM

Page 1

Item ID: D205-770-011 **Revision ID:** 

Required Date: 9/08/10

Replacement Engine Mount

Accept



Setup Start



Item Name: **Start Date:** 

9/08/10

Start Oty: 3.00 Req'd Qty: 3.00

**Cust Item ID: Customer:** 

Reference:

NCR10-330

OC:

Rework

Tooling:

Date:

Start

Run

Approvals:

**Process Plan:** 

Date: Date:

SPC (Y/N):

Date:

Stop

Stop

Sequence ID/ **Work Center ID**  **Operation** Description

**Revision Nbr** 

Set Up/ **Run Hours**  Tool ID

Tool # Plan Accept Qty Code

Reject Reject Qty Number

Insp. Stamp

**Draw Nbr** 

IIN D205-770 Rev B E

MDL-D205-770

0.00

DOCUMENT CONTROL

Memo

0.00

Document Control

Photocopy bluefile and create labels per PPP D205-770-011 CHG003

J'olor os

Small Fab

0.00

0.00

PULL FROM STOCK:
1 X D205-770-011 B61040
2 X D205-770-011 B61041

REWORK D3687-1 PER NCR10-330

Re-Driller Libe \$ 189" (+120rile) > Mh Wolonford

100

Small Fab

105

Page 2

September 8, 2010 8:31:43 AM

Item ID:

D205-770-011

Accept

Setup Start

Stop

Start



**Revision ID:** 

Item Name:

Replacement Engine Mount

**Start Date:** 

9/08/10

Start Oty: 3.00

**Req'd Qty: 3.00** 

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

NCR10-330

QC:

Date:

Tooling:

SPC (Y/N):

Date: Date:

Stop

Run

Sequence ID/

**Work Center ID** 

Required Date: 9/08/10

Operation

Set Up/ **Run Hours**  Tool ID

Tool # Plan Accept Code Qty

Reject Qty

Insp.

106

Quality Control

Description

QC5- Inspect part completeness to step on W/O

Reinstalled Anti-Sezi

Date:

- inspects with 0.00

Oby w Ansc-16 belts From stores.

+ D3688-5

107

Packaging

Memo

0.00

0.00

Packaging

108

QC4-100% Inspect kits for completeness

0.00

Memo

Quality Control

Reject Number

Stamp

RETURN PARTS TO KIT, ENSURE KIT IS COMPLETE



Page 3

September 8, 2010 8:31:44 AM

Item ID:

D205-770-011

Accept



Setup Start



**Revision ID:** 

Item Name:

Replacement Engine Mount

**Start Date:** 

9/08/10

Start Qty: 3.00

Req'd Qty: 3.00



**Cust Item ID:** 

**Customer:** 

Reference:

NCR10-330

Approvals:

Required Date: 9/08/10

**Process Plan:** 

Date: Date:

**Tooling:** 

Date:

Run

Start

Stop

QC:

SPC (Y/N):

Date:

Stop

Sequence ID/

**Work Center ID** 

Operation Description

Pick Kit

Set Up/

**Run Hours** 

Tool ID

Tool # Plan Accept Qty Code

Reject Qty

Reject Number Stamp

Insp.

110

Packaging Packaging

Memo

REPACKAGE PER PPP USING NEW B/N

**NEW LABELS REO'D** 

0.00

CH6003

120

Quality Control

OC4-100% Inspect kits for completeness

Packaging

Packaging

130

Packaging

Identify and pack for shipping as per PPP D205

Location:

PPP Rev:

# Work Order ID 61848

Page 4

September 8, 2010 8:31:44 AM

Item ID:

D205-770-011

Accept



Setup Start

**Revision ID:** 

Item Name:

Replacement Engine Mount

**Start Date:** 

Required Date: 9/08/10

9/08/10

Start Oty: 3.00

**Operation** 

Description

Req'd Qty: 3.00

**Cust Item ID:** 

**Customer:** 

Reference:

NCR10-330

Approvals:

**Process Plan:** 

QC:

Date: Date: **Tooling:** 

SPC (Y/N):

0.00

0.00

**Run Hours** 

Date: Date: Run

Start

Stop

Stop

Sequence ID/

Work Center ID

140

Memo

QC21- Final Inspection - Work Order Release

Set Up/ Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Reject Insp. Number,

Stamp

**Quality Control** 

N word

# Picklist Print

September 8, 2010 8:31:41 AM

Work Order ID: 61848

Parent Item:

D205-770-011

Parent Item Name:

Replacement Engine Mount





**Start Date:** 9/08/10

Required Date: 9/08/10

Page 1

Start Qty: 3.00

Required Qty: 3.00

**Comments:** 

IPP Rev:A new issue ECN1165p 08-03-31 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status	
D205-770-011		Manufactured	No			·	Each	3.0000		3				
										SB	15	09/0	8	

Replacement Engine Mount

Location		Loc Qty	Loc Code		
FG043		3			
	61040	1		1	
	61041	2			<u>~</u>

#### **Jason Murdoch**

From:

David Shepherd [dshepherd@dartaero.com]

Sent:

Thursday, September 02, 2010 3:52 PM

To:

'Marc Bellavance'
'Jason Murdoch'

Cc: Subject:

RE: D205-770-011 Replacement Engine Mount Kit

Attachments:

image002.jpg

Yes ... It is acceptable to open up the holes slightly. I do not feel an LPI is required after the rework.

David

From: Marc Bellavance [mailto:mbellavance@dartaero.com]

Sent: Thursday, September 02, 2010 1:43 PM

To: 'David Shepherd'
Cc: 'Jason Murdoch'

Subject: FW: D205-770-011 Replacement Engine Mount Kit

Importance: High

David,

Can you please have a look at this issue and advise.

Per Jason's investigation, the 0.189" holes on P/N D3687-1 are indeed too small (0.185" to 0.187") on pretty much all the parts we have in stock and therefore, it is impossible to insert the required bolts through.

Funny thing is, 2 legs out of 3 are assembled prior to packaging and it seems to Jason and me that the holes might have been reworked to tolerance during assembly. However, there is no non-conformance reported on the W/O's, no sign offs on the rework whatsoever.

We need to ship a replacement kit to Day Aviation who are not willing to rework the kit themselves ASAP per Eagle. Question is: can manufacturing has your authorization to rework the part so we can ship the Kit to our customer? Also, is LPI required after the rework?

Thanks,

# Marc Bellavance Mechanical Designer/Technical Support

# **DART** aerospace Ltd.

Tel: 613-632-5200 Ext. 240

Fax: 613-632-9311

E-mail: mbellavance@dartaero.com

Web: www.dartaero.com



Please consider your environmental responsibility before printing this e-mail

The information contained in this transmission is privileged and confidential and intended only for the use of the individual or entity to whom it is addressed. If you are not the intended recipient, you are hereby notified that any distribution, copying, disclosure or taking of any action in reliance on the contents of this transmission is strictly prohibited and review by any individual other than the intended recipient shall not constitute waiver of privilege. If you have received this transmission in error, please notify me immediately and delete the original transmission.

From: Jason Murdoch [mailto:jmurdoch@dartaero.com]

Sent: September 2, 2010 11:27 AM